

Mercron Repair Charges and Fees As of September 1, 2010

1. Minimum Bench Charge.....\$75 (MBC) Test and inspection only.
Includes visual inspection and testing, resetting of the thermal cutout if needed, and minor adjustments. Applies to units received with NFF (No Fault Found) and also to units not repairable due to physical damage.
2. Update Bench Charge..... \$120 (UBC) Circuit updates only.
This charge applies to older units that are functioning but require circuit updates (engineering changes) to restore their performance to original (or better) operation.
Additional charges may apply, see below.
3. Standard Bench Charge.....\$175 (SBC) Repairs to controller PCB only.
Includes all circuit board mounted components needed to return the unit to original functionality. All latest updates are installed and the unit is completely tested.
Additional charges may apply, see below.
4. No Box Bench Charge..... \$120 (NBC) Repairs to controller PCB only.
Applies to units configured without an enclosure. Includes all circuit board mounted components required for repair and updates, testing and adjustment.
5. Housing Bench Charge..... \$200 (HBC) Lamp Fixture and controller repair.
Applies to units returned installed in the Customer's custom housing or lamp enclosure.
Includes repair of Mercron Board plus inspection of photo detector positioning and adjustment of light intensity. Also includes cleaning of lamp and reflector.

Possible additions to UBC or SBC:

- Clean circuit board to remove contamination (CLN)..... \$30
- Replace damaged or nonfunctional enclosure (ENC).....\$30
- Replace cooling fan (FAN).....\$27
- Replace EMI filter (EMI).....\$15
- Removal of carbon trails on circuit board (from arcing) (CBN)..... \$30
- Completely refurbish unit (RFB)..... \$75

Includes: Wash and clean circuit board as needed
Repair and update circuit board as needed
New fan and finger guard
New input and output wiring
New enclosure and labeling